

(h) Related Information

Refer to MCAI European Aviation Safety Agency AD No. 2018–0217, dated October 10, 2018, for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1058. For service information related to this AD, contact PILATUS Aircraft Ltd., Customer Technical Support (MCC), P.O. Box 992, CH–6371 Stans, Switzerland; phone: +41 (0)41 619 67 74; fax: +41 (0)41 619 67 73; email: techsupport@pilatus-aircraft.com; internet: <http://www.pilatus-aircraft.com>. You may review this referenced service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on December 17, 2018.

Melvin J. Johnson,

Aircraft Certification Service, Deputy Director, Policy and Innovation Division, AIR–601.

[FR Doc. 2018–27899 Filed 12–21–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2018–1012; Product Identifier 2018–NM–132–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 777 airplanes. This proposed AD was prompted by reports of uncommanded movements of the Captain’s and First Officer’s seats. This proposed AD would require an identification of the part number, and if applicable the serial number, of the Captain’s and First Officer’s seats, and do applicable on-condition actions for affected seats. This proposed AD would also require a one-time detailed inspection and repetitive checks of the horizontal movement system of the Captain’s and First Officer’s seats and applicable on-condition actions. This proposed AD would also provide an optional terminating action for the repetitive checks of the horizontal movement system. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by February 11, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1012.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1012; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3569; email: Brandon.Lucero@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES**

section. Include “Docket No. FAA–2018–1012; Product Identifier 2018–NM–132–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports indicating that there have been uncommanded movements of the Captain’s and First Officer’s seats. A Model 747 operator reported that during a takeoff, the First Officer’s seat unlocked from its seat tracks and moved aft. The First Officer was unable to control the airplane and the Captain took over the controls to avoid a rejected takeoff. The unlocking of the seat from the seat tracks was caused by actuator damage, which was a result of incorrect adjustment of the seat’s manual release lever cable, which allowed the clutch mechanism to only partially engage. Captain’s and First Officer’s seats having the same part numbers are installed on both Model 747 and Model 777 airplanes. We are considering additional rulemaking to address the unsafe condition for Model 747 airplanes.

In addition, a Model 777 operator reported that the Captain’s seat could not be locked in position after an adjustment to the horizontal seat position in flight. The seat became unlocked from the track and moved freely forward and aft. Control was given to the First Officer for approach and landing. The results of an inspection revealed that the horizontal actuator output shaft had broken. When a horizontal actuator output shaft breaks, the pilot cannot prevent seat movement in a forward and aft direction and cannot lock the seat in position. A broken horizontal actuator output shaft is the result of high loads, that exceed the design limits, caused by a stalled motor that can occur due to high mechanical resistance to motion during powered operation of the seat. Foreign object debris (FOD) in the seat tracks is another condition that can result in a stalled motor and cause the horizontal actuator output shaft to break.

An uncommanded seat movement during a critical part of a flight, such as takeoff or landing, could cause a flight

control obstruction or unintended flight control input, which could result in the loss of the ability to control the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Special Attention Service Bulletin 777-25-0607, Revision 1, dated July 17, 2018 (“BSASB 777-25-0607, Revision 1”). The service information describes procedures for identification of the part number, and if applicable the serial number, of the Captain’s and First Officer’s seats, and for applicable on-condition actions for affected seats. The on-condition actions include an inspection of each seat’s fore/aft and vertical manual control levers for looseness, installation of serviceable seats, and a seat functional test after any cable adjustment.

We also reviewed Boeing Special Attention Service Bulletin 777-25-0619, Revision 1, dated August 8, 2018 (“BSASB 777-25-0619, Revision 1”). The service information describes procedures for a detailed inspection and repetitive checks of the horizontal movement system for the Captain’s and First Officer’s seats for findings (e.g., evidence of cracks, scores, corrosion, dents, deformation or visible wear; and incorrectly assembled microswitch assemblies, actuators, and limit switches), and applicable on-condition actions. The on-condition actions include clearing the seat tracks of FOD, overhaul of the horizontal movement system and replacement of the horizontal actuator. The service information also describes procedures for an optional terminating action for the repetitive checks by installing a serviceable Captain’s or First Officer’s seat.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified in the Accomplishment Instructions of BSASB 777-25-0607, Revision 1, described previously, except as discussed under “Differences Between this Proposed AD and the Service Information,” and except for any differences identified as exceptions in the regulatory text of this proposed AD.

This proposed AD would also require accomplishment of the actions identified as “RC” (required for compliance) in the Accomplishment Instructions of BSASB 777-25-0619, Revision 1, described previously, except as discussed under “Differences Between this Proposed AD and the Service Information,” and except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1012.

Differences Between This Proposed AD and the Service Information

The effectivity of BSASB 777-25-0607, Revision 1; and BSASB 777-25-0619, Revision 1, is limited to Model 777-200, -200LR, -300, -300ER, and 777F airplanes with Ipeco part number series 3A201 and 3A258 Captain’s and First Officer’s powered seats installed, line numbers 1 and on. However, the applicability of this proposed AD includes all Model 777-200, -200LR, -300, -300ER, and 777F series airplanes. Because the affected Captain’s and First Officer’s seats are rotatable parts, we have determined that these seats could later be installed on airplanes that were initially delivered with acceptable seats, thereby subjecting those airplanes to the unsafe condition. The referenced service bulletins can be used on airplanes not included in the service bulletin effectivity. This difference has been coordinated with Boeing.

Where BSASB 777-25-0607, Revision 1, specifies to do the actions within 72 months after the original issue date of the service bulletin, this proposed AD would require accomplishment of those actions within 36 months after the effective date of this AD. The 36-month compliance time corresponds with the compliance time in BSASB 777-25-0619, Revision 1. We have determined a 36-month compliance time is appropriate for doing the actions specified in this proposed AD. We have coordinated this difference with Boeing.

Costs of Compliance

We estimate that this proposed AD affects 190 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS PER SEAT

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Identification, seat	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$85.
Detailed inspection, horizontal movement system.	1 work-hour × \$85 per hour = \$85	0	\$85	\$85.
Checks, horizontal movement system	2 work-hour × \$85 per hour = \$170 per check cycle.	0	\$170 per check cycle.	\$170 per check cycle.

We estimate the following costs to do any necessary on-condition actions that would be required. We have no way of

determining the number of aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS PER SEAT *

Action	Labor cost	Parts cost	Cost per product
Adjustment, control lever cable	1 work-hour × \$85 per hour = \$85	\$0	\$85.
Overhaul, horizontal movement system	11 work-hours × \$85 per hour = \$935	Up to \$5,824	Up to \$6,759.

ESTIMATED COSTS OF ON-CONDITION ACTIONS PER SEAT *—Continued

Action	Labor cost	Parts cost	Cost per product
Inspection of each seat's fore/aft and vertical manual control levers.	1 work-hour × \$85 per hour = \$85	\$0	\$85.
Installation of serviceable seats	1 work-hour × \$85 per hour = \$85	\$0	\$85.
Clearing FOD	1 work-hour × \$85 per hour = \$85	\$0	\$85.
Replacement of the horizontal actuator	1 work-hour × \$85 per hour = \$85, per actuator	\$205	\$290.
Functional test, adjusted control lever cable	1 work-hour × \$85 per hour = \$85	\$0	\$85.

* The estimated cost for tooling to align an affected seat for adjustment of the control lever cable is up to \$46,064.

We have received no definitive data that would enable us to provide cost estimates for the optional terminating action for the repetitive checks specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2018–1012; Product Identifier 2018–NM–132–AD.

(a) Comments Due Date

The FAA must receive comments on this AD action by February 11, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by reports of uncommanded movements of the Captain's and First Officer's seats. We are issuing this AD to address uncommanded movement of the Captain's and First Officer's seats. An uncommanded seat movement during a critical part of a flight, such as takeoff or landing, could cause a flight control obstruction or unintended flight control input, which could result in the loss of the ability to control the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Seat Part Number Identification and On-Condition Actions

Within 36 months after the effective date of this AD, do an inspection to determine the part number, and serial number as applicable, of the Captain's and First Officer's seats, and do all applicable on-condition actions, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777–25–0607, Revision 1, dated July 17, 2018.

(h) Detailed Inspection and Repetitive Checks of Horizontal Movement System and On-Condition Actions

Except as specified in paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 777–25–0619, Revision 1, dated August 8, 2018 ("BSASB 777–25–0619, Revision 1"), do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of BSASB 777–25–0619, Revision 1.

(i) Exception to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where BSASB 777–25–0619, Revision 1, uses the phrase "the original issue date of this service bulletin," this AD requires using "the effective date of this AD."

(j) Optional Terminating Action for Repetitive Checks

Installation of a serviceable Captain's or First Officer's seat as specified in, and in

accordance with the Accomplishment Instructions of BSASB 777–25–0619, Revision 1, terminates the repetitive checks required by paragraph (h) of this AD for that seat only.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3569; email: Brandon.Lucero@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA,

Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on December 14, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–27901 Filed 12–21–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF EDUCATION

34 CFR Chapter VI

[Docket ID ED–2018–OPE–0076]

RIN 1840–AD36, 1840–AD37, 1840–AD38, 1840–AD40, and 1840–AD44

Negotiated Rulemaking Committee; Location of Negotiations and Subcommittee Meetings—Accreditation and Innovation

AGENCY: Office of Postsecondary Education, Department of Education.

ACTION: Notice of location of negotiations and subcommittee meetings.

SUMMARY: On October 15, 2018, we announced our intention to establish a negotiated rulemaking committee to prepare proposed regulations for the Federal Student Aid programs authorized under title IV of the Higher Education Act of 1965, as amended (HEA). In this notice, we announce the locations of each committee and subcommittee meeting.

DATES: Please see the **SUPPLEMENTARY INFORMATION** section for meeting dates.

ADDRESSES: Please see the **SUPPLEMENTARY INFORMATION** section for meeting locations.

FOR FURTHER INFORMATION CONTACT: Aaron Washington, U.S. Department of Education, 400 Maryland Ave. SW, Room 294–12, Washington, DC 20202. Telephone (202) 453–7241. Email: Aaron.Washington@ed.gov.

If you use a telecommunications device for the deaf (TDD) or text telephone (TTY), call the Federal Relay Service (FRS), toll free, at 1–800–877–8339.

SUPPLEMENTARY INFORMATION:

Locations for Negotiations and Subcommittee Meetings

The Accreditation and Innovation Committee will meet for three sessions on the following dates:

Session 1: January 14–16, 2019
Session 2: February 19–22, 2019
Session 3: March 25–28, 2019

Sessions will run from 9:00 a.m. to 5:00 p.m.

The January committee meeting will be held at the U.S. Department of Education at: Lyndon Baines Johnson (LBJ) Building Barnard Auditorium, 400 Maryland Avenue SW, Washington, DC 20202.

The February committee meeting will be held at the U.S. Department of Education at: Potomac Center Plaza (PCP) Auditorium, 550 12th Street SW, Washington, DC 20202.

The March committee meeting will be held at the U.S. Department of Education at: LBJ Building Barnard Auditorium, 400 Maryland Avenue SW, Washington, DC 20202.

The committee meetings are open to the public to attend in person. The committee meetings will also be made available to the public through a Department-provided livestream.

The Distance Learning and Educational Innovation Subcommittee will meet for three meetings on the following dates:

Meeting 1: January 17–18, 2019
Meeting 2: February 12–13, 2019
Meeting 3: March 11–12, 2019

Meetings will run from 9:00 a.m. to 5:00 p.m.

The subcommittee meetings will be held at the U.S. Department of Education at: LBJ Building, 400 Maryland Ave. SW, Washington, DC 20202.

The January meeting will be held in room 1W113. The February meeting will be held in room 1W103. The March meeting will be held in room 1W126.

The Faith-Based Entities Subcommittee will meet for three meetings on the following dates:

Meeting 1: January 17–18, 2019
Meeting 2: February 12–13, 2019
Meeting 3: March 11–12, 2019

Meetings will run from 9:00 a.m. to 5:00 p.m.

The subcommittee meetings will be held at the U.S. Department of Education at: LBJ Building, 400 Maryland Ave. SW, Washington, DC 20202.

The January meeting will be held in room 297–05. The February meeting will be held in room 297–05. The March meeting will be held in room 1W113.

The TEACH Grant Subcommittee will meet for three meetings on the following dates:

Meeting 1: January 17–18, 2019
Meeting 2: February 12–13, 2019
Meeting 3: March 11–12, 2019

Meetings will run from 9:00 a.m. to 5:00 p.m.

The subcommittee meetings will be held at the U.S. Department of