

# Proposed Rules

Federal Register

Vol. 87, No. 203

Friday, October 21, 2022

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-1300; Project Identifier MCAI-2022-00663-T]

RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A321-251NX, A321-252NX, A321-253NX, A321-271NX and A321-272NX airplanes. This proposed AD was prompted by an emergency exit slide deployment test on an Airbus Cabin Flex (ACF) overwing emergency exit, the emergency exit slide did not deploy due to disconnected slide release cable junction. This proposed AD would require a one-time detailed inspection of the installation of the ACF overwing emergency exit slide release mechanism for discrepancies, and applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 5, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-1300.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-1300; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

#### FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3229; email [Vladimir.Ulyanov@faa.gov](mailto:Vladimir.Ulyanov@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-1300; Project Identifier MCAI-2022-00663-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing

date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3229; email [Vladimir.Ulyanov@faa.gov](mailto:Vladimir.Ulyanov@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0090, dated May 18, 2022 (also referred to as the MCAI), to correct an unsafe condition for certain Airbus SAS Model A321-251NX, A321-252NX, A321-253NX, A321-271NX and A321-272NX airplanes.

This proposed AD was prompted by an emergency exit slide deployment test on an Airbus SAS Model A321neo Cabin Flex (ACF) overwing emergency exit, where the emergency exit slide did not deploy. The investigation identified that the slide release mechanism cable

junction was disconnected inside the surrounding collets and knurled sleeve nut. The mushroom head connector was not inserted into the T-slot cable joint. The FAA is proposing this AD to address the disconnected slide release cable junction, which could prevent emergency slide deployment, possibly resulting in injury to occupants during an emergency evacuation. See the MCAI for additional background information.

**Related Service Information Under 14 CFR Part 51**

EASA AD 2022-0090 specifies procedures for a one-time detailed inspection of the installation of the ACF overwing emergency exit slide release mechanism on both left hand (LH) and right hand (RH) sides of the fuselage for discrepancies (*i.e.*, a disconnected slide release cable inside the sleeve nuts and collets (mushroom head not inserted in T-slot joint) and missing lockwire around the knurled sleeve nut), and applicable corrective actions. The corrective actions include connecting the slide release cable and installing lockwire on the knurled sleeve nut.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in EASA AD 2022-0090 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

**Explanation of Required Compliance Information**

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating

this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2022-0090 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2022-0090 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2022-0090 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2022-0090. Service information required by EASA AD 2022-0090 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-1300 after the FAA final rule is published.

**Costs of Compliance**

The FAA estimates that this proposed AD would affect 65 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
14 work-hours × \$85 per hour = \$1,190 .....	*\$0	\$1,190	\$77,350

\*The FAA has received no definitive data on which to base the cost estimates for the parts specified in this proposed AD.

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on the results of any optional actions. The FAA has no way of determining the number of aircraft that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
12 work-hours × \$85 per hour = \$1,020 ...	Negligible	\$1,020

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not

have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus SAS:** Docket No. FAA–2022–1300; Project Identifier MCAI–2022–00663–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 5, 2022.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Airbus SAS Model A321–251NX, A321–252NX, A321–253NX, A321–271NX and A321–272NX airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2022–0090, dated May 18, 2022 (EASA AD 2022–0090).

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Unsafe Condition

This AD was prompted by an emergency exit slide deployment test on an Airbus Cabin Flex (ACF) overwing emergency exit, where the emergency exit slide did not deploy due to a disconnected slide release cable junction. The FAA is issuing this AD to address the disconnected slide release cable junction, which could prevent emergency slide deployment, possibly resulting in injury to occupants during an emergency evacuation. See the mandatory continuing airworthiness information (MCAI) for additional background information.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0090.

#### (h) Exceptions to EASA AD 2022–0090

(1) Where EASA AD 2022–0090 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2022–0090 does not apply to this AD.

(3) Where paragraph (2) of EASA AD 2022–0090 specifies compliance times for corrective actions, for this AD, perform those corrective actions at the applicable times specified in paragraph (h)(3)(i), (ii), and (iii) of this AD.

(i) If missing lockwire around the knurled sleeve nut is found and the slide release cable inside the sleeve nuts and collets is connected (mushroom head inserted in T-slot joint): Install lockwire within 4 months after the effective date of this AD.

(ii) If a disconnected slide release cable inside the sleeve nuts and collets (mushroom head not inserted in T-slot joint) is found and lockwire around the knurled sleeve nut is not missing: Connect slide release cable before further flight.

(iii) If a disconnected slide release cable inside the sleeve nuts and collets (mushroom head not inserted in T-slot joint) is found and the lockwire around the knurled sleeve nut is missing: Connect slide release cable and install lockwire before further flight.

#### (i) No Reporting Requirement

Although the service information referenced in EASA AD 2022–0090 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD, if any service information referenced in EASA AD 2022–0090 contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not

identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

#### (k) Related Information

(1) For EASA AD 2022–0090, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–1300.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3229; email [Vladimir.Ulyanov@faa.gov](mailto:Vladimir.Ulyanov@faa.gov).

Issued on October 6, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022–22201 Filed 10–20–22; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2022–0141; Project Identifier MCAI–2021–01052–T]

RIN 2120–AA64

#### Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Supplemental notice of proposed rulemaking (SNPRM).

**SUMMARY:** The FAA is revising a notice of proposed rulemaking (NPRM) that would have applied to all MHI RJ Aviation ULC Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes. This action revises the NPRM by proposing to require an inspection for correct installation of the flexible lamp assembly; trimming and reidentifying a bracket; and for certain airplanes, an inspection for damage of