

(30) days to April 11, 2023 is consistent with the public interest, and that good cause exists for taking this action.

Accordingly, the comment period for Notice No. 23-05 is extended until April 11, 2023.

Issued under authority provided by 49 U.S.C. 106(f), 44701(a), and 44703 in Washington, DC.

Kimberly R. Pyle,

Executive Director, Office of Accident Investigation and Prevention, Federal Aviation Administration.

[FR Doc. 2023-01788 Filed 1-27-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-0028; Project Identifier MCAI-2022-01164-T]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2022-03-12, which applies to all Airbus SAS Model A330-200, -300, -800, and -900 series airplanes; and Model A340-200, -300, -500, and -600 series airplanes. AD 2022-03-12 requires replacing the doghouse door lock placard with an improved instruction placard. Since the FAA issued AD 2022-03-12, it has been determined that additional parts need to be modified. This proposed AD would continue to require the actions in AD 2022-03-12 and would expand the list of affected parts, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). This proposed AD would also prohibit the installation of affected parts under certain conditions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by March 16, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2023-0028; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For the EASA AD identified in this NPRM, you may contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu*; website *easa.europa.eu*. You may find this material on the EASA website at *ad.easa.europa.eu*. It is also available at *regulations.gov* under Docket No. FAA-2023-0028.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229; email *vladimir.ulyanov@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-0028; Project Identifier MCAI-2022-01164-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments

received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229; email *vladimir.ulyanov@faa.gov*. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2022-03-12, Amendment 39-21929 (87 FR 8169, February 14, 2022) (AD 2022-03-12), for all Airbus SAS Model A330-200, -300, -800, and -900 series airplanes; and Model A340-200, -300, -500, and -600 series airplanes. AD 2022-03-12 was prompted by an MCAI originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued AD 2021-0136, dated June 4, 2021 (EASA AD 2021-0136), to correct an unsafe condition.

AD 2022-03-12 requires replacing the doghouse door lock placard with an improved instruction placard. AD 2022-03-12 also prohibits the installation of affected parts under certain conditions. The FAA issued AD 2022-03-12 to address possible incorrect operation of the doghouse door lock due to unclear and incomplete handling instructions on the door placard installed near the lock. This condition, if not addressed, could lead to failure of the latch, which could block the door in the closed position and prevent access to the emergency equipment inside the doghouse.

Actions Since AD 2022–03–12 Was Issued

Since the FAA issued AD 2022–03–12, EASA superseded EASA AD 2021–0136, and issued AD 2022–0179, dated August 26, 2022 (EASA AD 2022–0179) (also referred to as the MCAI), to correct an unsafe condition for all Airbus SAS A330–201, A330–202, A330–203, A330–223, A330–243, A330–301, A330–302, A330–303, A330–321, A330–322, A330–323, A330–341, A330–342, A330–343, A330–841, A330–941, A340–211, A340–212, A340–213, A340–311, A340–312, A340–313, A340–541, A340–542, A340–642, and A340–643 airplanes. Model A340–542 and A340–643 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

The MCAI states that the instructions on the doghouse door lock placard are unclear and incomplete, and could lead to incorrect operation of the lock. This condition, if not corrected, could lead to failure of the latch, blocking the door in the closed position and preventing access to emergency equipment, possibly resulting in injury to airplane occupants. Since EASA AD 2021–0136 was issued, it has been determined that additional parts need to be modified.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–0028.

Explanation of Retained Requirements

Although this proposed AD does not explicitly restate the requirements of AD 2022–03–12, this proposed AD would retain all of the requirements of AD 2022–03–12. Those requirements are referenced in EASA AD 2022–0179,

which, in turn, is referenced in paragraph (g) of this proposed AD.

Related Service Information Under 1 CFR Part 51

EASA AD 2022–0179 specifies procedures for replacing the doghouse door lock placard with an improved instruction placard. EASA AD 2022–0179 also prohibits the installation of doghouses with incorrect instruction placards. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would retain all requirements of AD 2022–03–12. This proposed AD would require accomplishing the actions specified in EASA AD 2022–0179 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD. This proposed AD would also prohibit the installation of affected parts under certain conditions.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2022–0179 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2022–0179 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2022–0179 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2022–0179. Service information required by EASA AD 2022–0179 for compliance will be available at *regulations.gov* under Docket No. FAA–2023–0028 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 62 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170.	Up to \$95 per placard	Up to \$265 per placard	Up to \$16,430.*

* Assuming one placard per product. The number of placards on an airplane depends on the passenger configuration and varies from operator to operator.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section

44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

■ a. Removing Airworthiness Directive (AD) 2022–03–12, Amendment 39–21929 (87 FR 8169, February 14, 2022); and

■ b. Adding the following new AD:

Airbus SAS: Docket No. FAA–2023–0028; Project Identifier MCAI–2022–01164–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by March 16, 2023.

(b) Affected ADs

This AD replaces AD 2022–03–12, Amendment 39–21929 (87 FR 8169, February 14, 2022) (AD 2022–03–12).

(c) Applicability

This AD applies to all Airbus SAS airplanes, certificated in any category, as identified in paragraphs (c)(1) through (8) of this AD.

(1) Model A330–201, –202, –203, –223, and –243 airplanes.

(2) Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes.

(3) Model A330–841 airplanes.

(4) Model A330–941 airplanes.

(5) Model A340–211, –212, and –213 airplanes.

(6) Model A340–311, –312, and –313 airplanes.

(7) Model A340–541 airplanes.

(8) Model A340–642 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by reports that the instructions on the doghouse door lock placard are unclear and incomplete, and by a determination that additional parts need to be modified. The FAA is issuing this AD to address possible incorrect operation of the doghouse door lock due to unclear and incomplete handling instructions on the door placard installed near the lock. The unsafe condition, if not addressed, could result in failure of the latch, which could block the door in the closed position and prevent access to the emergency equipment inside the doghouse.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0179, dated August 26, 2022 (EASA AD 2022–0179).

(h) Exceptions to EASA AD 2022–0179

(1) Where EASA AD 2022–0179 refers to June 18, 2021 (the effective date of EASA AD 2021–0136), this AD requires using March 21, 2022 (the effective date of AD 2022–03–12).

(2) Where EASA AD 2022–0179 refers to its effective date, this AD requires using the effective date of this AD.

(3) Although EASA AD 2022–0179 specifies to “remove the placard and install an improved handling instructions placard on each affected part,” this AD requires replacing the placard on each affected part with an improved handling instructions placard.

(4) This AD does not adopt the “Remarks” section of EASA AD 2022–0179.

(i) Additional FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229; email vladimir.ulyanov@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0179, dated August 26, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0179, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on January 25, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–01835 Filed 1–27–23; 8:45 am]

BILLING CODE 4910–13–P